

Pressure Conversion Chart for PSI to Bar:

Pressure Conversion Chart, PSI to BAR

<u>PSI</u>	<u>BAR</u>	<u>PSI</u>	<u>BAR</u>	<u>PSI</u>	<u>BAR</u>	<u>PSI</u>	<u>BAR</u>	<u>PSI</u>	<u>BAR</u>
1	0.07	25	1.72	49	3.38	73	5.03	97	6.69
2	0.14	26	1.79	50	3.45	74	5.1	98	6.76
3	0.21	27	1.86	51	3.52	75	5.17	99	6.83
4	0.28	28	1.93	52	3.59	76	5.24	100	6.9
5	0.34	29	2	53	3.65	77	5.31	105	7.24
6	0.41	30	2.07	54	3.72	78	5.38	110	7.58
7	0.48	31	2.14	55	3.79	79	5.45	115	7.93
8	0.55	32	2.21	56	3.86	80	5.52	120	8.27
9	0.62	33	2.28	57	3.93	81	5.59	125	8.62
10	0.69	34	2.34	58	4	82	5.65	130	8.89
11	0.76	35	2.41	59	4.07	83	5.72	135	9.31
12	0.83	36	2.48	60	4.14	84	5.79	140	9.65
13	0.9	37	2.55	61	4.21	85	5.86	145	10.1
14	0.97	38	2.62	62	4.28	86	5.93	150	10.34
15	1.03	39	2.69	63	4.34	87	6	155	10.69
16	1.1	40	2.76	64	4.41	88	6.07	160	11.03
17	1.17	41	2.83	65	4.48	89	6.14	165	11.38
18	1.24	42	2.9	66	4.55	90	6.21	170	11.72
19	1.31	43	2.97	67	4.62	91	6.27	175	12.07
20	1.38	44	3.03	68	4.69	92	6.34	180	12.41
21	1.45	45	3.1	69	4.76	93	6.41	185	12.76
22	1.52	46	3.17	70	4.83	94	6.48	190	13.1
23	1.59	47	3.24	71	4.9	95	6.55	195	13.45
24	1.65	48	3.31	72	4.97	96	6.62	200	13.79